




CONDENSATION ON
INSIDE OF
WEATHERSTRIP. WARM
AIR CONDENSING ON
COLD FRAME.



WATER CONDENSING ON INTERIOR
SIDE OF WEATHERSTRIPPING. WATER
TRAPPED AND STAINS WOOD FRAME.



WATER CONDENSATION
ON WINDOW HEAD
INTERIOR AND EXTERIOR
OF WEATHERSTRIP.

STAINED WOOD INTERIOR DUE TO
WATER CONDENSATION ON
INTERIOR OF FRAME BEING
TRAPPED AND ABSORBED BY WOOD.

