


Main Design Flaws:

1. Exhaust Only Ventilation. If bathroom vents or range hood is not running, house is not ventilating.
2. No dedicated Dehumidifier

Simple (initial) Proposal



Manufacturer Recommendations

