



FIGURE 4.10
A timber beam that burns through in a prolonged fire is likely to topple its supporting masonry wall (left) unless its end is firecut (right). The beam is anchored to the wall in each case by a steel strap anchor of the type shown in Figure 4.13